

To: CN=Dominic Digiulio/OU=ADA/O=USEPA/C=US@EPA;CN=Rick Wilkin/OU=ADA/O=USEPA/C=US@EPA[]; N=Rick Wilkin/OU=ADA/O=USEPA/C=US@EPA[]
Cc: []
From: CN=Gregory Oberley/OU=R8/O=USEPA/C=US
Sent: Thur 6/14/2012 3:46:35 PM
Subject: Fw: memos re DRO in Phase 2
[DRO Overlays with Field Blank, Sample, and Lab Blank.pdf](#)
[Pavillion BPA memo.docx](#)
[Pavillion DRO Field Blank memo.pdf](#)
[Blank Contamination Memo.pdf](#)

I haven't looked at these yet but they should be what you're looking for.

Gregory Oberley
Aquifer Protection Team
US EPA Region VIII (EP-EPR)
1595 Wynkoop Street
Denver, Colorado 80202

303-312-7043

----- Forwarded by Gregory Oberley/R8/USEPA/US on 06/14/2012 09:46 AM -----

From: Robert Parker/R8/USEPA/US
To: Gregory Oberley/R8/USEPA/US@EPA
Date: 06/13/2012 04:32 PM
Subject: memos re DRO in Phase 2

Greg,

per your request, here are the memos that discuss the DRO blank issue in Phase 2.

DRO Overlays for chromatogram review

Memo from Jesse Kiernan to me (which I've turned into a PDF)

A memo from me to ATSDR discussing blank contamination

Rob Parker
Site Assessment Manager, Environmental Engineer
U.S. Environmental Protection Agency, Region 8
Address: 1595 Wynkoop St, 8EPR-SA, Denver, Colorado 80202-1129
Email: parker.robert@epa.gov | Direct Phone: (303) 312-6664